



Type	Luminous intensity indicator
Measurement range	0.01 ~ 50.000 lux
Multiplier	2.000 lux: x10 reading 50.000 lux: x100 reading

Light Meter

