



Type	TRUE RMS digital amperometric clamp
DC voltage measurement	600 Vdc
AC voltage measurement	600 Vac
Current DC measurement	1000 A
Current AC measurement	1000 A
resistance Measurement	40 M Ω
Capacity	40 μ F
Frequency	4 kHz
Temperature	1000°C/1832°F
Continuity buzzer	100 Ω