

Phase rotation indicator



Type

Three-phase rotation indicator

- direction of rotation
- direction of rotation without contact
- magnetic direction
- determines the motor connections