

TRUE RMS digital multimeter and wireless isolation meter



Type	TRUE RMS Digital Multimeter and Wireless insulation meter
DC voltage measurement	1000 Vdc
AC voltage measurement	1000 Vac
Current DC measurement	10 A
Current AC measurement	10 A
resistance Measurement	40 MΩ
Capacity	40 mF
Temperature (K type)	4-20mA%

